


A BRITISH COMPANY SUPPORTING BRITISH CARS

WIPER MOTOR

Triumph Spitfire & 1500

Part Number: **517621**

The wiper motor drive pinion gear (sometimes referred to a as a gear wheek and shaft) together with the rack slide, is not supplied and is required to be transferred from the old unit.



QUALITY PARTS AND ACCESSORIES



Triumph House, Sleaford Road, Bracebridge Heath, Lincoln LN4 2NA, England UK Tel: +44 (0)1522 568000 | USA Tel: 1 855 746 2767 | Fax: +44 (0)1522 567600 | E-mail: sales@rimmerbros.com

www.rimmerbros.com

Registered in England No. 2155394



A BRITISH COMPANY SUPPORTING BRITISH CARS

Refer to figure and remove the four gearboxes retaining screws (1), and lift away the cover (2). Release the circlip and flat washer (3), securing the connecting rod to the crack pin (10), then lift away the connecting rod (4) followed by the second flat washer (5).

Release the circlip and washer (11) securing the shaft and gear to the gearbox body. Remove any burrs from around the circle groove (12). Lift away the gear wheel and shaft (6) making a careful note of the location and dished washer (7).

Inspect the gear wheel and shaft (6) for signs of excessive wear or damage, and fit a new one if necessary. Lift out and transfer to the wiper motor the rack slide.

Reassemble components to the wiper motor in the reverse procedure to dismantling.

Before fitting the wiper motor, a check should be made of the vehicle wiper system, i.e., wheel-box and drive-rack (8) for freedom of movement, Nd to ensure no strain or damage has occurred which will affect performance.

RECOMMENDED USE OF WIPERS AFTER FITTING REPLACEMENT WIPER MOTOR

- 1. Wipers should not be run continuously on a dry screen.
- 2. Clear all snow from windscreen before operating wipers.
- 3. Release frozen wiper blades from windscreen before operating wipers. Failure to observe the above recommendations can result in premature wipe motor failure which may invalidate the warranty.

QUALITY PARTS AND ACCESSORIES



Triumph House, Sleaford Road, Bracebridge Heath, Lincoln LN4 2NA, England UK Tel: +44 (0)1522 568000 | USA Tel: 1 855 746 2767 | Fax: +44 (0)1522 567600 | E-mail: sales@rimmerbros.com

www.rimmerbros.com

Registered in England No. 2155394